



VEHICLE INSPECTION REPORT

GP19RVM

Ford Fiesta 1.0 EcoBoost 140 ST-Line 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	31/07/2019	VIN	WF0JXXGAHJKY03140	CAP Average	£6,650.00
Year	2019	Body Style	Hatchback	CAP Below	£5,750.00
Mileage	38,270 Miles Warranted	Keys	1	Gearbox	MANUAL
Fuel Type	Petrol	MOT Due	30/07/2025	Gears	6
Colour	BLUE	CAP Clean	£7,550.00	Doors	5



£65 ADDITIONAL FEE

Tyres		
NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	2.0mm
OSR	MICHELIN	3.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- ABS
- Side airbags
- Cloth seat trim
- Rear parking sensor
- Digital radio
- Climate control
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Over 50mm

No Image

No Image

5: Wing nsf
Scratched
Over 25mm Not Thru Paint

6: Door nsf
Scratched
Over 25mm Not Thru Paint

No Image



7: Door nsr
Scratched
Over 25mm Not Thru Paint


8: Qtr Panel nsr
Chipped
1 To 5



9: Wheel nsr
Scratched
Over 50mm



10: Bumper Rear
Chipped
Multiple Chips




11: Bumper Rear
Scratched
Over 25mm Not Thru Paint



12: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



13: Wheel osr
Scratched
Over 50mm



14: Door osr
Scratched
Over 25mm Not Thru Paint

No Image


No Image

15: Door osf
Scratched
Over 25mm Not Thru Paint

16: Wing osf
Scratched
Over 25mm Not Thru Paint



17: Wheel osf
Scratched
Over 50mm



18: Screen Front
Cracked
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK