



VEHICLE INSPECTION REPORT

BD09OSE

Ford C-Max 1.6 Zetec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	16/07/2009	Keys	1	CAP Clean	£530.00
Year	2009	Service history	Yes	CAP Average	£200.00
Mileage	149,184 Miles Warranted	Service documents	Service Book	CAP Below	£200.00
Fuel Type	Petrol	Number of stamps	6	Gearbox	MANUAL
Colour	BLUE	Last service date	07/07/2020	Gears	5
VIN	WF0EXXGCDE9P15842	Last service miles	90,672		
Body Style	MPV	MOT Due	17/07/2025		

£50 ADDITIONAL FEE. LAST SERVICE 7/7/20 @ 90672 MILES (6 SERVICES 2 MAIN DEALER) BOOK

Tyres


NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	3.0mm
OSR	BRIDGESTONE	2.0mm
Spare		

Features


- PAS
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear wiper
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- ABS
- Side airbags
- Alloy wheels
- Radio/CD
- Climate control
- Rear headrests
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bumper Front
Cracked
Over 25mm



2: Bumper Front Grill
Broken
Replace



3: Bonnet
Chipped
1 To 5



4: Wheel nsf
Scratched
Over 50mm




5: Wing nsf
Chipped
1 To 5



6: Door nsf
Dented
With Paint Damage



7: Door nsr
Dented
2 Or Less UpTo 10mm



8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Qtr Panel nsr
Rusted
Over 5mm




10: Wheel nsr
Scratched
Over 50mm



11: Bumper Rear
Scratched
Over 100mm Thru Paint



12: Boot Lid
Dented
Over 2 UpTo 10mm



13: Boot Lid
Scratched
Over 25mm Not Thru Paint




14: Qtr Panel osr
Rusted
Over 5mm




15: Wheel osr
Scratched
Over 50mm




16: Door osr
Dented
Between 10mm + 30mm




17: Door osr
Scratched
Over 25mm Not Thru Paint



18: Door osf
Chipped
1 To 5



19: Door osf
Scratched
Over 25mm Not Thru Paint



20: Wing osf
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK