

VEHICLE INSPECTION REPORT

FX16DLU

Kia Sorento 2.2 CRDi KX-4 5dr Auto

Inspection	No	Vehicle			nama
Serious Damage?		VAT	Margin		2 Grape
		V5	Present		
Details					
Reg. date	11/08/2016	Keys	2	CAP Clean	£9,950.00
Year	2016	Service history	Yes	CAP Average	£8,825.00
Mileage	105,542 Miles Warranted	Service documents	Service Book	CAP Below	£7,700.00
		Number of stamps	8	Gearbox	AUTOMATIC
Fuel Type	Diesel	Last service date	07/10/2024	Gears	6
Colour	BLACK	Last service miles	95,426		
VIN	KNAPH81BSG5190395		05/08/2025		
Body Style	Estate		33, 33, 2320	<u> </u>	

£100 ADDITIONAL FEE. Last Service: 07/10/2024 at 95426 miles. (8 services (7 main dealer))

Tyres

NSF	CONTINENTAL	3.0mm	
NSR	HANKOOK	3.0mm	
OSF	CONTINENTAL	3.0mm	
OSR	HANKOOK	4.0mm	_
Spare			

Features

- Bluetooth connection
- Navigation systemTelephone
- Electric sunroof
- seat
- Rear headrests
- Passenger airbagRemote central locking
- Cruise control
- Park assist camera
- Radio/CD
- Air conditioning
- Metallic Paint
- Traction control
- · Leather seat trim
- Front parking sensor
- Rear parking sensorBody coloured bumpers
- Climate control
- Front electric windows
- Tyre pressure monitorAlloy wheels

- Heated front seat
- Rear wiper
- Electric door mirrors
- Electric door mirrors
 Electrically adjustable drivers seat
 Rear electric windows
- Drivers airbag
- Central locking

Photos























Condition Check



Damage Photos



1: Seat Base Cover osf Torn Over 3mm



2: Wheel osf Scratched Over 50mm



3: Wheel nsf Scratched Over 50mm



4: Wing osf Chipped 1 To 5




5: Wing osf Scratched Over 25mm Not Thru Paint




6: Door osf Chipped 1 To 5



7: Door nsr Scratched Over 25mm Not Thru Paint



8: Door nsr Chipped 1 To 5



9: Door nsf Chipped 1 To 5



10: Wing nsfScratchedOver 25mm Not Thru Paint



11: Bumper FrontScratchedOver 25mm Not Thru Paint



12: BonnetChipped1 To 5

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		