

#### 46 Brampton Road Eastbourne **BN22 9BN** 01323 520295 | no-reply@ebca.co.uk

# **VEHICLE INSPECTION REPORT**

LY08PFU

## Vauxhall Corsa 1.4i 16V Club 5dr Auto [AC]

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		GRADE CRADE
		V5	Present		
Details					
Reg. date	14/08/2008	Keys	2	CAP Clean	£1,050.00
Year	2008	Service history	Yes	CAP Average	£640.00
Mileage	76,698 Miles Warranted	Service documents	Printout	CAP Below	£275.00
		Number of stamps	9	Gearbox	AUTOMATIC
Fuel Type	Petrol	Last service date	30/11/2024	Gears	5
Colour	BLUE	Last service miles	70,506	Doors	5
VIN	W0L0SDL6884479145	MOT Due	07/12/2025		
Body Style	Hatchback		0.7.12,2020		

### £100 ADDITIONAL FEE. Last Service: 30/11/2024 at 70506 miles. (9 services )

Tyres			
NSF	BUDGET	5.0mm	
NSR	HIFLY	5.0mm	
OSF	BUDGET	5.0mm	
OSR	ROVELO	5.0mm	
Spare			

٠

## **Features**

- PAS
- PAS
  Body coloured bumpers
  Front head restraints
  3x3 point rear seat belts
  Passenger airbag
  Alloy wheels

- Rear wiper Electric door mirrors Height adjustable drivers seat ٠
- ABŠ Central locking
- ٠ Rear headrests
  - •
  - Drivers airbag Remote central locking .
- Steering wheel mounted controls Radio/CD Air conditioning Front elec
  - Front electric windows
  - Solid Paint
  - Isofix child seat anchor pointsPartial leather seat trim

### **Photos**










## **Condition Check**



## **Damage Photos**



1: Bonnet Chipped 1 To 5



2: Wing nsf Scratched Over 25mm Thru Paint







5: Door nsf Chipped Edge Chip



4: Door Mirror Assy nsf Scratched (Painted) Over 25mm Thru Paint



6: Qtr Panel nsr Poor Previous Repair Poor Paint



7: Wheel nsr Scratched Over 50mm



8: Bumper Rear Scratched Over 100mm Thru Paint



9: Qtr Panel osr Dented With Paint Damage



11: Door osf Scratched Over 25mm Thru Paint



13: Door nsr Poor Previous Repair Rippled UpTo 30%

Interior



10: Door Moulding osr Scratched (Painted) UpTo 25mm Thru Paint



12: Wheel osf Scratched Over 50mm



14: Seat Base Cover osf Scuffed Over 25mm

### **Vehicle Inspection Report**

#### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	ОК	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	ОК	Gearbox Static Gear Selection (engine running)	
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK