



VEHICLE INSPECTION REPORT

GD54HFY

Toyota Avensis 2.0 VVT-i T Spirit 5dr Seq Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	22/09/2004	Body Style	Hatchback	Last service miles	67,622
Year	2004	Keys	2	MOT Due	22/09/2025
Mileage	70,989 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Petrol	Service documents	Printout	Gears	4
Colour	SILVER	Number of stamps	3	Doors	5
VIN	SB1DJ56L70E040855	Last service date	19/04/2024		

£65 ADDITIONAL FEE. LAST SERVICE 19/4/24 @ 67622 MILES (3 SERVICE) PRINT Rough running and eml on
Front bumper misaligned

Tyres

NSF	KUMHO	2.0mm
NSR	NEXEN	4.0mm
OSF	BUDGET	Damaged
OSR	NEXEN	4.0mm
Spare		

Features


- PAS
- Radio/Cassette
- Climate control
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking
- Rear wiper
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Leather seat trim
- Steering wheel mounted controls
- Electric door mirrors
- Electrically adjustable passenger seat
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Audio remote control
- Air conditioning
- Front armrest
- Rear electric windows
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Other
N/A
N/A



2: Bonnet
Chipped
1 To 5




3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Chipped
1 To 5



6: Wing nsf
Scratched
Over 25mm Not Thru Paint



7: Screen Front
Chipped
UpTo 10mm



8: Door nsf
Dented
Between 10mm + 30mm



9: Door nsr
Dented
Over 30mm



10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Chipped
1 To 5



12: Bumper Rear
Scratched
Over 100mm Thru Paint



13: Boot Lid
Dented
2 Or Less Up To 10mm



14: Qtr Panel osr
Chipped
1 To 5

No Image



15: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

16: Wheel osr
Scratched
Over 50mm



17: Door osr
Chipped
1 To 5



18: Door osf
Dented
Between 10mm + 30mm



19: Wing osf
Chipped
1 To 5



20: Wheel osf
Scratched
Over 50mm

No Image

21: Tyre osf
Damaged
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Poor
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK