



VEHICLE INSPECTION REPORT

LN11VYA

Mercedes-Benz E Class E250 CDI BlueEFFICIENCY Avantgarde 5dr Tip Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	
		V5	Present

nama
GRADE
3

Details

Reg. date	29/03/2011	Body Style	Estate	Last service miles	97,380
Year	2011	Keys	2	MOT Due	24/04/2026
Mileage	99,230 Miles Warranted	Service history	Yes	CAP Clean	£3,200.00
Fuel Type	Diesel	Service documents	Printout	CAP Average	£2,800.00
Colour	SILVER	Number of stamps	9	CAP Below	£2,425.00
VIN	WDD2122032A381253	Last service date	17/04/2025		

£65 ADDITIONAL FEE. 9 services, last 17/04/2025

Tyres


NSF	SUNNY	Damaged
NSR	SUNNY	4.0mm
OSF	BUDGET	4.0mm
OSR	SUNNY	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Audio remote control
- Electric sunroof
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Cruise control
- Rear parking sensor
- Radio/CD
- Opening panoramic glass roof
- Front electric windows
- Rear electric windows
- ABS
- Traction control
- Alloy wheels
- Front parking sensor
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Central locking
- Heated front seat
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
Over 25mm Thru Paint

No Image

6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsr
Chipped
1 To 5

No Image

8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Wheel nsr
Scratched
Over 50mm

No Image

10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



11: Bumper Rear
Scratched
Over 100mm Thru Paint

No Image

12: Boot Lid
Scratched
Over 25mm Not Thru Paint



13: Wheel osr
Scratched
Up To 50mm

No Image


14: Door osr
Scratched
Over 25mm Not Thru Paint



15: Door osf
Chipped
1 To 5




16: Wheel osf
Scratched
Over 50mm



17: Screen Front
Chipped
UpTo 10mm



18: Other
N/A
N/A



19: Tyre nsf
Damaged
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		