

## **VEHICLE INSPECTION REPORT**

LG16ZRF

## Ford Ranger Limited 4x4 Dcb Td - 2198cc

		V5	
Serious Damage?	No	VAT	Plus VAT
Inspection		Vehicle	



#### **Details**

Reg. date	02/06/2016	Fuel Type	Diesel	Gearbox	AUTOMATIC
Year	2016	Colour	Black	_	
Mileage	142,397 miles Not	VIN	6FPPXXMJ2PGR48002		
	Warranted				

#### NON-RUNNER Front bumper misaligned

ı	y	re	S
k		_	

NSF

NSR

OSF

**OSR** 

**Spare** 

### **Features**

- Bluetooth connection
- Rear parking sensor
- Audio remote control
- Electric door mirrors
- Electrically adjustable drivers seat Front armrest
- Rear electric windows
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels

- · Cruise control
- Steering wheel mounted controls Telephone
- Auxiliary input socket
- Front fog lights
- · Rear headrests
- · Isofix child seat anchor points
- Central locking
- · Park assist camera
- Digital radio
- Air conditioning Front electric windows
- Solid Paint
- Passenger airbag
- Remote central locking
- PAS
- Trip computer
- Body coloured bumpers
- Climate control
- Rear armrest
- 3x3 point rear seat belts
- Traction control
- · Leather seat trim

#### **Photos**






















## **Condition Check**



## **Damage Photos**



1: Seat Base Cover osf Torn Over 3mm



2: Bonnet Chipped 1 To 5

## No Image

3: Bonnet Scratched Over 25mm Not Thru Paint



4: Bumper Front Scratched Over 100mm Thru Paint



5: Wheel nsf Corroded Light



6: Wing nsf Chipped Multiple Chips



7: Door nsf Scratched Over 25mm Thru Paint



8: Door nsr Dented With Paint Damage



9: Qtr Panel nsr Dented With Paint Damage



10: Wheel nsf Scratched Over 50mm



11: Boot Lid Dented With Paint Damage

## No Image

12: Bumper Rear Scratched Over 25mm Not Thru Paint



13: Qtr Panel osr Dented With Paint Damage



14: Door osr Dented With Paint Damage



15: Wheel osr Scratched Over 50mm




16: Door osr Chipped 1 To 5

# No Image

17: Wing osf Scratched Over 25mm Not Thru Paint



18: Wing osf Rusted Over 5mm



19: Screen Front Chipped UpTo 10mm



20: Roof Chipped Multiple Chips

#### Interior

**Carpet Condition Seat Condition** 

Average Poor **Upholstery Condition Odour** 

Average No

### **Vehicle Inspection Report**

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
		Steering	OK