



VEHICLE INSPECTION REPORT

AF60YFM

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
4

Details

Reg. date 08/10/2010

Year 2010

Mileage 191,817 Miles
Warranted

Fuel Type Diesel

Colour GREY

VIN YV1CZ7146B1579490

Body Style Estate

Keys 2

Service history Yes

Service documents Service Book

Number of stamps 13

Last service date 24/09/2024

Last service miles 183,247

MOT Due 16/10/2025

CAP Clean £1,500.00

CAP Average £1,100.00

CAP Below £700.00

Gearbox AUTOMATIC

Gears 6

£65 ADDITIONAL FEE LAST SERVICE 24/9/24 @ 183247 MILES (13 SERVICE 10 MAIN DEALER) BOOK
Noise from underneath left screen on dash fault

Tyres

NSF PIRELLI Worn

NSR PIRELLI 3.0mm

OSF PIRELLI 2.0mm

OSR PIRELLI 3.0mm


Spare

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Leather seat trim
- PAS
- Audio remote control
- Electric sunroof
- Electrically adjustable drivers seat
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Rear parking sensor
- Radio/CD
- Opening panoramic glass roof
- Front armrest
- Rear electric windows
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Poor Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Up To 50mm

No Image



5: Wing nsf
Scratched
Over 25mm Not Thru Paint

6: Door nsf
Dented
Over 2 UpTo 10mm




7: Door nsf
Chipped
1 To 5



8: Door nsr
Dented
With Paint Damage



9: Qtr Panel nsr
Chipped
1 To 5




10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint




11: Wheel nsr
Scratched
Over 50mm



12: Bumper Rear
Scratched
25 to 100mm Thru Paint



13: Bumper Rear
Scratched
Over 25mm Not Thru Paint



14: Boot Lid
Scratched
Over 25mm Not Thru Paint

No Image



15: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

16: Wheel osr
Scratched
Up To 50mm



17: Door osr
Dented
With Paint Damage



18: Door osf
Chipped
1 To 5

No Image

19: Door osf
Scratched
Over 25mm Not Thru Paint

No Image


20: Wing osf
Scratched
Over 25mm Not Thru Paint



21: Wheel osf
Scratched
Over 50mm



22: Seat Base Cover osf
Torn
Over 3mm



23: Tyre nsf
Worn
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK