



VEHICLE INSPECTION REPORT

OU13CJZ

Honda Accord 2.4 i-VTEC EX 4dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	17/06/2013	Keys	1	CAP Clean	£2,850.00
Year	2013	Service history	Yes	CAP Average	£2,375.00
Mileage	131,978 Miles Warranted	Service documents	Printout	CAP Below	£1,925.00
Fuel Type	Petrol	Number of stamps	12	Gearbox	MANUAL
Colour	GREY	Last service date	08/12/2023	Gears	6
VIN	JHMCU2500DC209015	Last service miles	125,849	Doors	4
Body Style	Saloon	MOT Due	08/04/2026		

LAST SERVICE 8/12/23 @ 125849 MILES (12 SERVICE) PRINT
NO V5 GREEN SLIP EX POLICE CAR

Tyres

NSF	GOODYEAR	3.0mm
NSR	GOODYEAR	4.0mm
OSF	GOODYEAR	4.0mm
OSR	BUDGET	6.0mm

Spare

Features


- Cruise control
- Park assist camera
- Radio/CD
- Front fog lights
- Front parking sensor
- PAS
- Body coloured bumpers
- Air conditioning
- Heated front seat
- Rear parking sensor
- Electric door mirrors
- Electrically adjustable drivers seat
- Navigation system
- Steering wheel mounted controls
- Electric sunroof
- Electrically adjustable passenger seat
- Folding rear seats
- Rear electric windows
- ABS
- Central locking
- Front armrest
- Rear headrests
- Drivers airbag
- Remote central locking
- Front electric windows
- Metallic Paint
- ESP
- Leather seat trim
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint



2: Wheel of
Corroded
Light



3: Wing nsf
Chipped
Multiple Chips



4: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Dented
With Paint Damage



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Dented
Between 10mm + 30mm



10: Bumper Rear
Dented
With Paint Damage



11: Tailgate
Scratched
UpTo 25mm Thru Paint



12: Wheel nsr
Scratched
Over 50mm



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint



14: Door osr
Scratched
Over 25mm Thru Paint




15: Door nsf
Scratched
Over 25mm Thru Paint



16: Wing osf
Dented
With Paint Damage



17: Wheel osf
Corroded
Light



18: Bonnet
Dented
Over 30mm



19: Seat Back Cover osf
Scuffed
Over 25mm



20: Switches And Controls
Broken
Replace

Interior

Carpet Condition
Seat Condition

Average
Poor

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK