



VEHICLE INSPECTION REPORT

GN65XSF

Peugeot 208 1.2 PureTech 82 Active 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	11/09/2015	Keys	1	CAP Clean	£1,875.00
Year	2015	Service history	Yes	CAP Average	£1,450.00
Mileage	64,029 Miles Warranted	Service documents	Service Book	CAP Below	£1,025.00
Fuel Type	Petrol	Number of stamps	4	Gearbox	MANUAL
Colour	BLUE	Last service date	13/05/2022	Gears	5
VIN	VF3CAHMZ6FT159741	Last service miles	42,620	Doors	3
Body Style	Hatchback	MOT Due	31/01/2026		

LAST SERVICE 13/5/22 @ 42620 MILES (4 SERVICE) BOOK

Tyres

NSF	BUDGET	2.0mm
NSR	NEXEN	2.0mm
OSF	RIKEN	2.0mm
OSR	NEXEN	4.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Cruise control
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- ABS
- Side airbags
- Alloy wheels
- PAS
- Digital radio
- Climate control
- Rear headrests
- Drivers airbag
- Central locking
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wheel osf
Scratched
Up To 50mm




4: Wing osf
Chipped
1 To 5



5: Wing osf
Scratched
Over 25mm Not Thru Paint



6: Door osf
Dented
Between 10mm + 30mm



7: Door osf
Scratched
Over 25mm Not Thru Paint



8: Qtr Panel osr
Dented
Between 10mm + 30mm

No Image

9: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

10: Wheel osr
Scratched
Up To 50mm



11: Bumper Rear
Scratched
Over 100mm Thru Paint



12: Boot Lid
Chipped
1 To 5



13: Wheel nsr
Scratched
Up To 50mm



14: Qtr Panel nsr
Chipped
1 To 5

No Image



15: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

16: Door nsf
Chipped
1 To 5

No Image



17: Door nsf
Scratched
Over 25mm Not Thru Paint

18: Wing nsf
Scratched
Over 25mm Thru Paint



19: Wheel nsf
Scratched
Up To 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK