



VEHICLE INSPECTION REPORT

MV14GZY

Ford Focus 1.0 EcoBoost Zetec Navigator 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	15/03/2014	Keys	2	CAP Clean	£2,025.00
Year	2014	Service history	Yes	CAP Average	£1,600.00
Mileage	78,070 Miles Warranted	Service documents	Service Book	CAP Below	£1,150.00
Fuel Type	Petrol	Number of stamps	8	Gearbox	MANUAL
Colour	RED	Last service date	23/10/2024	Gears	5
VIN	WF0KXXGCBKEL51044	Last service miles	72,399	Doors	5
Body Style	Hatchback	MOT Due	26/10/2025		

£100 ADDITIONAL FEE. LAST SERVICE 23/10/24 @ 72399 MILES (8 SERVICE 1 MAIN DEALER) BOOK AND PRINT

Tyres


NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Audio remote control
- Air conditioning
- Front electric windows
- Solid Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Radio/CD
- Climate control
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- ABS
- Side airbags
- Alloy wheels
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Rear headrests
- Drivers airbag
- Central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Poor Previous Repair
Poor Colour



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Poor Previous Repair
Poor Paint



5: Door nsf
Dented
Between 10mm + 30mm



6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsr
Chipped
Multiple Chips



8: Wheel nsr
Scratched
Over 50mm

No Image



9: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

10: Bumper Rear
Scratched
25 to 100mm Thru Paint

No Image

No Image

11: Bumper Rear
Scratched
Over 25mm Not Thru Paint


12: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



13: Door osr
Chipped
1 To 5

No Image

14: Door osr
Scratched
Over 25mm Not Thru Paint



15: Door osf
Chipped
1 To 5

16: Door osf
Scratched
Over 25mm Not Thru Paint



17: Wing osf
Dented
Between 10mm + 30mm

18: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK