



VEHICLE INSPECTION REPORT

GU67VPV

Ford B-Max 1.0 EcoBoost 125 Titanium Navigator 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	13/10/2017	Keys	2	CAP Clean	£5,200.00
Year	2017	Service history	Yes	CAP Average	£4,475.00
Mileage	32,426 Miles Warranted	Service documents	Service Book	CAP Below	£3,750.00
Fuel Type	Petrol	Number of stamps	7	Gearbox	MANUAL
Colour	WHITE	Last service date	10/09/2024	Gears	5
VIN	WF0KXXERJKHB79910	Last service miles	29,443		
Body Style	MPV	MOT Due	12/10/2025		

Last Service - 10.09.2024 at 29443 miles (7 main dealer services)

Tyres


NSF	GOODYEAR	2.0mm
NSR	GOODYEAR	3.0mm
OSF	GOODYEAR	2.0mm
OSR	GOODYEAR	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Central locking
- PAS
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Radio/CD
- Climate control
- Rear electric windows
- ABS
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips

No Image

3: Bumper Front
Scratched
Over 25mm Not Thru Paint



4: Wheel osf
Scratched
Up To 50mm

No Image

5: Wing osf
Scratched
Over 25mm Not Thru Paint



6: Door osf
Chipped
1 To 5



7: Door osr
Chipped
1 To 5

No Image

8: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



9: Bumper Rear
Chipped
Multiple Chips

No Image

10: Bumper Rear
Scratched
Over 25mm Not Thru Paint

No Image

11: Boot Lid
Scratched
Over 25mm Not Thru Paint

No Image

12: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



13: Wheel nsr
Scratched
Up To 50mm



14: Door nsr
Dented
2 Or Less UpTo 10mm

No Image



15: Door nsr
Scratched
Over 25mm Not Thru Paint

16: Door nsf
Dented
Between 10mm + 30mm

No Image



17: Door nsf
Scratched
Over 25mm Not Thru Paint

18: Wing nsf
Chipped
1 To 5



19: Wheel nsf
Scratched
Up To 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK