



VEHICLE INSPECTION REPORT

GV11HCG

Toyota Auris 1.8 VVTi Hybrid T Spirit 5dr CVT Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	21/06/2011	Keys	2	CAP Clean	£4,875.00
Year	2011	Service history	Yes	CAP Average	£4,275.00
Mileage	74,059 Miles Warranted	Service documents	Service Book	CAP Below	£3,650.00
Fuel Type	Hybrid Electric	Number of stamps	11	Gearbox	CVT
Colour	BLUE	Last service date	13/12/2023	Gears	1
VIN	SB1KS56E80E038814	Last service miles	64,098	Doors	5
Body Style	Hatchback	MOT Due	21/12/2025		

Last Service - 13.12.2023 at 64098 miles (11 services 9 main dealer services)

Tyres



NSF	LAUFENN	1.0mm
NSR	LAUFENN	4.0mm
OSF	LAUFENN	3.0mm
OSR	LAUFENN	4.0mm
Spare		

Features


- Cruise control
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Traction control
- Alloy wheels
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Park assist camera
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim

Photos





Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint



2: Bonnet
Chipped
Over 5mm



3: Wheel nsf
Scratched
Over 50mm




4: Wing nsf
Chipped
1 To 5



5: Door Mirror Assy nsf
Broken
Replace



6: Door nsf
Chipped
1 To 5



7: Door nsf
Scratched
Over 25mm Not Thru Paint



8: Door nsr
Scratched
Over 25mm Thru Paint




9: Qtr Panel nsr
Dented
With Paint Damage




10: Wheel nsr
Scratched
Over 50mm



11: Bumper Rear
Poor Previous Repair
Rippled UpTo 30%



12: Boot Lid
Scratched
Over 25mm Not Thru Paint



13: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



14: Wheel osr
Scratched
Over 50mm

No Image



15: Door osf
Scratched
Over 25mm Not Thru Paint

16: Door osf
Scratched
Over 25mm Thru Paint



17: Wheel osf
Scratched
Over 50mm



18: Screen Front
Chipped
UpTo 10mm

No Image

19: Tyre nsf
Less Than 1.6mm
Illegal

No Image

20: Tyre nsf
Less Than 1.6mm
Illegal

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK