



# VEHICLE INSPECTION REPORT

**WR15NHG**

## Skoda Rapid Spaceback 1.6 TDI CR SE Tech 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	01/05/2015	Keys	2	CAP Clean	£3,650.00
Year	2015	Service history	Yes	CAP Average	£3,125.00
Mileage	57,455 Miles Warranted	Service documents	Printout	CAP Below	£2,625.00
Fuel Type	Petrol	Number of stamps	7	Gearbox	MANUAL
Colour	SILVER	Last service date	13/03/2025	Gears	5
VIN	TMBFT6NH3F4532847	Last service miles	56,443	Doors	5
Body Style	Hatchback	MOT Due	09/06/2026		

£100 ADDITIONAL FEE.

Last Service -13.03.2025 at 56443 miles (7 services)

NO GREEN SLIP

### Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	HANKOOK	3.0mm
OSR	BUDGET	4.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Alloy wheels
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

## Photos






## Condition Check



## Damage Photos



1: Bumper Rear  
Chipped  
Multiple Chips



2: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint





3: Qtr Panel nsr  
Dented  
Between 10mm + 30mm



4: Wheel nsr  
Scratched  
Up To 50mm



5: Door nsr  
Dented  
2 Or Less UpTo 10mm



6: Door nsf  
Dented  
Over 30mm



7: Wing nsf  
Dented  
Over 2 UpTo 10mm



8: Bumper Front  
Poor Previous Repair  
Poor Paint




9: Screen Front  
Chipped  
UpTo 10mm



10: Wheel nsf  
Scratched  
Over 50mm




11: Wheel osf  
Scratched  
Over 50mm



12: Door osf  
Scratched  
Over 25mm Not Thru Paint



13: Wing osf  
Scratched  
UpTo 25mm Thru Paint



14: Door osr  
Scratched  
Over 25mm Not Thru Paint

No Image



15: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint

16: Wheel osr  
Scratched  
Up To 50mm

No Image

17: Boot Lid  
Scratched  
Over 25mm Not Thru Paint

## Interior

**Carpet Condition**      Average  
**Seat Condition**      Average

**Upholstery Condition**      Average  
**Odour**      No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK