



VEHICLE INSPECTION REPORT

AU68FYP

Mazda CX-5 2.2d [184] Sport Nav+ 5dr Auto AWD

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	20/12/2018	Body Style	Estate	MOT Due	06/06/2026
Year	2018	Keys	2	CAP Clean	£13,100.00
Mileage	51,641 Miles Warranted	Service history	Yes	CAP Average	£11,850.00
Fuel Type	Diesel	Service documents	Printout	CAP Below	£10,600.00
Colour	RED	Number of stamps	1	Gearbox	AUTOMATIC
VIN	JMZKFGW2A00778260	Last service date	04/10/2024	Gears	6

£65 ADDITIONAL FEE. Last service 04/10/2024 (mileage not recorded). (1 service)

Tyres

NSF	BUDGET	5.0mm
NSR	TOYO	3.0mm
OSF	BUDGET	6.0mm
OSR	BUDGET	6.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Climate control
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Electric sunroof
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels
- Front parking sensor
- PAS
- Radio/CD
- Front fog lights
- Electrically adjustable passenger seat
- Front head restraints
- Metallic Paint
- ESP
- Central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Scratched (Painted)
UpTo 25mm Thru Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Bonnet
Scratched
Over 25mm Not Thru Paint



5: Wing nsf
Poor Previous Repair
Rippled UpTo 30%



6: Door nsf
Poor Previous Repair
Poor Paint



7: Door nsr
Poor Previous Repair
Rippled UpTo 30%



8: Qtr Panel nsr
Dented
Over 30mm



9: Tailgate
Scratched
Over 25mm Not Thru Paint



10: Bumper Rear
Scratched
25 to 100mm Thru Paint



11: Qtr Panel nsr
Dented
Between 10mm + 30mm



12: Door Moulding osr
Scratched (Painted)
UpTo 25mm Thru Paint



13: Door osf
Dented
Between 10mm + 30mm



14: Wheel osf
Scratched
Over 50mm



15: Wing osf
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		