



VEHICLE INSPECTION REPORT

LG14JWW

Ford Fiesta 1.0 Zetec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	27/03/2014	Keys	2	CAP Clean	£2,300.00
Year	2014	Service history	Yes	CAP Average	£1,800.00
Mileage	102,558 Miles Warranted	Service documents	Service Book	CAP Below	£1,350.00
Fuel Type	Petrol	Number of stamps	10	Gearbox	MANUAL
Colour	Black	Last service date	02/04/2025	Doors	5
VIN	WF0DXXGAKDEY42157	Last service miles	96,592		
Body Style	Hatchback	MOT Due	02/04/2026		

Last Service - 02.04.2024 at 96592 miles (10 services)

Tyres

NSF	GT RADIAL	4.0mm
NSR	SAILUN	3.0mm
OSF	GT RADIAL	4.0mm
OSR	SAILUN	3.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Solid Paint
- Isofix child seat anchor points
- Alarm
- Alloy wheels
- PAS
- Trip computer
- Body coloured bumpers
- Climate control
- Rear electric windows
- 3x3 point rear seat belts
- Passenger airbag
- Central locking
- Rear wiper
- Audio remote control
- Electric door mirrors
- Front electric windows
- Rear headrests
- ABS
- Rear airbags
- Remote central locking
- Steering wheel mounted controls
- Auxiliary input socket
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- Drivers airbag
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2:



3: Bumper Front
Chipped
Multiple Chips



4: Bumper Front
Scratched
Over 25mm Not Thru Paint



5: Wing osf
Chipped
1 To 5



6: Wheel osf
Scratched
Over 50mm



7: Door osf
Dented
With Paint Damage



8: Door osf
Dented
With Paint Damage




9: Qtr Panel osr
Chipped
1 To 5



10: Wheel osr
Scratched
Up To 50mm



11: Bumper Rear
Scratched
Over 100mm Thru Paint



12: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



13: Door nsr
Dented
With Paint Damage




14: Door nsf
Dented
With Paint Damage



15: Wheel nsr
Scratched
Up To 50mm



16: Wing nsf
Scratched
Over 25mm Not Thru Paint



17: Roof
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK