



# VEHICLE INSPECTION REPORT

YF22NWO

## Vauxhall Crossland 1.5 Turbo D Design 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Photocopy



### Details

Reg. date	09/06/2022	Body Style	Hatchback	CAP Below	£6,225.00
Year	2022	Keys	1	Gearbox	MANUAL
Mileage	46,965 Miles Warranted	Service history	None	Gears	6
Fuel Type	Diesel	MOT Due	08/06/2026	Doors	5
Colour	WHITE	CAP Clean	£8,275.00		
VIN	W0V7D9EN0N4171249	CAP Average	£7,250.00		

V5 is a photocopy DPF light intermittent

### Tyres

NSF	FALKEN	3.0mm
NSR	BRIDGESTONE	4.0mm
OSF	BUDGET	5.0mm
OSR	BRIDGESTONE	5.0mm
Spare		

## Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Digital radio
- Climate control
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
Multiple Chips



No Image

3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



4: Wheel nsf  
Scratched  
Over 50mm

No Image

5: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



6: Door nsf  
Dented  
Between 10mm + 30mm



7: Door nsr  
Chipped  
1 To 5



8: Wheel nsr  
Scratched  
Up To 50mm

No Image

9: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint

No Image

10: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint

No Image

11: Boot Lid  
Scratched  
Over 25mm Not Thru Paint



12: Wheel osr  
Scratched  
Over 50mm



13: Door osr  
Scratched  
UpTo 25mm Thru Paint

No Image

14: Door osr  
Scratched  
Over 25mm Not Thru Paint



15: Door osf  
Chipped  
1 To 5



16: Wheel osf  
Scratched  
Up To 50mm

## Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK