



VEHICLE INSPECTION REPORT

FL15MZZ

Lexus CT 200h 1.8 Advance 5dr CVT Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	17/04/2015	Keys	2	CAP Clean	£5,875.00
Year	2015	Service history	Yes	CAP Average	£5,125.00
Mileage	121,124 Miles Warranted	Service documents	Printout	CAP Below	£4,375.00
Fuel Type	Hybrid Electric	Number of stamps	5	Gearbox	CVT
Colour	BLUE	Last service date	13/11/2020	Gears	1
VIN	JTHK5BH502234621	Last service miles	71,937	Doors	5
Body Style	Hatchback	MOT Due	12/02/2026		

MILEAGE OF SERVICE IN 2018 NOT RECORDED

last service 13/11/20 @ 71,937 miles, 5 services (all 5 main dealer services)

Tyres

NSF	FIRESTONE	3.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	3.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Traction control
- Alloy wheels
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5




5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsf
Dented
Between 10mm + 30mm



7: Door nsr
Chipped
1 To 5



8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



11: Bumper Rear
Poor Previous Repair
Paint Flake



12: Boot Lid
Chipped
1 To 5



13: Qtr Panel osr
Chipped
1 To 5




14: Wheel osr
Scratched
Over 50mm



15: Door osr
Chipped
1 To 5

No Image

16: Door osr
Scratched
Over 25mm Not Thru Paint



17: Door osf
Chipped
1 To 5

No Image

18: Wing osf
Scratched
Over 25mm Not Thru Paint



19: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK