



VEHICLE INSPECTION REPORT

OV60WYJ

Honda CR-V 2.0 i-VTEC ES 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	17/11/2010	Keys	2	CAP Clean	£1,600.00
Year	2010	Service history	Yes	CAP Average	£1,200.00
Mileage	175,030 Miles Warranted	Service documents	Service Book	CAP Below	£775.00
Fuel Type	Petrol	Number of stamps	10	Gearbox	MANUAL
Colour	SILVER	Last service date	01/08/2024	Gears	6
VIN	SHSRE5750AU017156	Last service miles	167,741		
Body Style	Estate	MOT Due	Expired		

£65 ADDITIONAL FEE. Last service 01/08/2024 at 167741 miles. (10 services (5 main dealer). Front bumper misaligned

Tyres


NSF	AVON	4.0mm
NSR	BUDGET	2.0mm
OSF	AVON	4.0mm
OSR	BUDGET	3.0mm
Spare		

Features


- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking
- Heated front seat
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Partial leather seat trim
- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Poor Previous Repair
Paint Flake




3: Bumper Front Grill
Broken
Replace



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Chipped
1 To 5



6: Wing nsf
Scratched
Over 25mm Not Thru Paint



7: Door Mirror Assy nsf
Broken
Replace



8: Door nsf
Dented
Between 10mm + 30mm



9: Door nsr
Dented
With Paint Damage




10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Chipped
1 To 5



12: Bumper Rear
Scratched
Over 100mm Thru Paint



13: Boot Lid
Scratched
Over 25mm Not Thru Paint



14: Wheel osr
Scratched
Over 50mm



15: Qtr Panel osr
Scratched
Over 25mm Thru Paint



16: Door osr
Scratched
Over 25mm Thru Paint



17: Door osf
Poor Previous Repair
Poor Paint



18: Wing osf
Poor Previous Repair
Poor Paint



19: Wheel osf
Scratched
Over 50mm



20: Fogdriving Lamp nsf
Broken
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK