



VEHICLE INSPECTION REPORT

GM14HHW

Vauxhall Adam 1.2i Jam 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	24/06/2014	Keys	1	CAP Clean	£1,525.00
Year	2014	Service history	Yes	CAP Average	£1,125.00
Mileage	123,978 Miles Warranted	Service documents	Service Book	CAP Below	£725.00
Fuel Type	Petrol	Number of stamps	3	Gearbox	MANUAL
Colour	RED	Last service date	10/10/2019	Gears	5
VIN	W0L0MAP08E6075767	Last service miles	80,125	Doors	3
Body Style	Hatchback	MOT Due	09/10/2025		

£100 ADDITIONAL FEE. Last service 10/10/2019 at 80125 miles, 3 services (2 main dealer services)

Tyres


NSF	SUNNY	4.0mm
NSR	BUDGET	5.0mm
OSF	SUNNY	4.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- ABS
- Side airbags
- Cloth seat trim
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Paint Flake



2: Bumper Front
Poor Previous Repair
Paint Flake



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



6: Door nsf
Dented
Over 30mm



7: Wheel nsr
Scratched
Over 50mm



8: Tailgate
Scratched
Over 25mm Thru Paint



9: Bumper Rear
Chipped
Multiple Chips



10: Wheel osr
Scratched
Over 50mm



11: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



12: Door osf
Scratched
Over 25mm Thru Paint



13: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Not Thru Paint



14: Wing osf
Dented
With Paint Damage



15: Roof
Chipped
1 To 5

16: Qtr Panel nsr
Dented
With Paint Damage

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK