



VEHICLE INSPECTION REPORT

CK66LZJ

Citroen C4 Cactus 1.2 PureTech [110] Flair Edition 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	21/11/2016	Keys	2	CAP Clean	£4,000.00
Year	2016	Service history	Yes	CAP Average	£3,450.00
Mileage	48,734 Miles Warranted	Service documents	Service Book	CAP Below	£2,925.00
Fuel Type	Petrol	Number of stamps	7	Gearbox	MANUAL
Colour	RED	Last service date	06/11/2024	Gears	5
VIN	VF70PHNZBGE567892	Last service miles	45,462	Doors	5
Body Style	Hatchback	MOT Due	20/11/2025		

Last Service - 06.11.2024 at 45462 miles (7 services) tapping from engine

Tyres

NSF	LAUFENN	3.0mm
NSR	GOODYEAR	Worn
OSF	LAUFENN	3.0mm
OSR	BUDGET	3.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Digital radio
- Air conditioning
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Climate control
- Height adjustable drivers seat
- ABS
- Side airbags
- Partial leather seat trim
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- PAS
- Audio remote control
- Fixed panoramic glass roof
- Front electric windows
- Solid Paint
- Isofix child seat anchor points
- Central locking

Photos






Condition Check



Damage Photos



1: Bumper Rear
Chipped
Multiple Chips



2: Bumper Rear
Scratched
Over 25mm Not Thru Paint

No Image



3: Boot Lid
Scratched
Over 25mm Not Thru Paint

4: Door osr
Dented
Over 2 UpTo 10mm



5: Door osf
Dented
Over 2 UpTo 10mm



6: Bonnet
Chipped
1 To 5

No Image



7: Wing osf
Scratched
Over 25mm Not Thru Paint

8: Wheel osf
Scratched
Up To 50mm



9: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image


10: Bumper Front
Scratched
Over 25mm Not Thru Paint

No Image

11: Wing nsf
Scratched
Over 25mm Not Thru Paint



12: Wheel nsf
Scratched
Over 50mm



13: Door nsf
Chipped
1 To 5

No Image

14: Door nsf
Scratched
Over 25mm Not Thru Paint

No Image



15: Door nsr
Scratched
Over 25mm Not Thru Paint

16: Wheel nsr
Scratched
Up To 50mm

No Image

No Image

17: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

18: Tyre nsr
Worn
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK