



VEHICLE INSPECTION REPORT

LL15NHV

Nissan Qashqai 1.2 DiG-T N-Tec+ 5dr Xtronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	29/05/2015	Keys	1	CAP Clean	£5,175.00
Year	2015	Service history	Yes	CAP Average	£4,525.00
Mileage	67,414 Miles Warranted	Service documents	Service Book	CAP Below	£3,850.00
Fuel Type	Petrol	Number of stamps	6	Gearbox	CVT
Colour	RED	Last service date	06/09/2024	Gears	1
VIN	SJNFEAJ11U1421546	Last service miles	64,123	Doors	5
Body Style	Hatchback	MOT Due	14/07/2026		

LAST SERVICE 6/9/24 @ 64123 MILES (6 SERVICE 3 MAIN DEALER) BOOK Eml intermittent
Rough running and gearbox fault
Exhaust blowing/ smoking
Brakes fault

Tyres

NSF	BUDGET	2.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	2.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Park assist camera
- Audio remote control
- Electric sunroof
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Digital radio
- Fixed panoramic glass roof
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wheel nsf
Scratched
Up To 50mm




4: Wing nsf
Chipped
1 To 5




5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsf
Chipped
Multiple Chips



7: Door nsr
Dented
2 Or Less UpTo 10mm



8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Wheel nsr
Scratched
Over 50mm




10: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



11: Bumper Rear
Poor Previous Repair
Paint Flake



12: Boot Lid
Chipped
1 To 5



13: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



14: Wheel osr
Scratched
Over 50mm



15: Door osr
Dented
Over 2 UpTo 10mm



16: Door osf
Poor Previous Repair
Poor Paint



17: Wing osf
Dented
Over 2 UpTo 10mm



18: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	Fault	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	Fault

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK