



VEHICLE INSPECTION REPORT

MX63CZT

Vauxhall Astra 1.7 CDTi 16V ecoFLEX 130 Exclusiv 5dr [SS]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/11/2013	Keys	2	CAP Clean	£1,425.00
Year	2013	Service history	Yes	CAP Average	£1,025.00
Mileage	88,216 Miles Warranted	Service documents	Service Book	CAP Below	£625.00
Fuel Type	Diesel	Number of stamps	11	Gearbox	MANUAL
Colour	SILVER	Last service date	01/07/2025	Gears	6
VIN	W0LPD8EH0E8019364	Last service miles	88,123		
Body Style	Estate	MOT Due	08/09/2025		

LAST SERVICE 1/7/25 @ 88123 MILES (11 SERVICE 4 MAIN DEALER) BOOK AND PRINT
CAMBELT DONE 14/8/22 @ 68685 MILES
NEW CLUTCH FITTED ON 15/7/24 @ 83708 MILES

Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Radio/CD
- Climate control
- Rear electric windows
- ABS
- Side airbags
- Steel wheels

Photos






Condition Check



Damage Photos



1: Bumper Rear
Scratched
25 to 100mm Thru Paint



2: Bumper Rear
Scratched
Over 25mm Not Thru Paint

No Image



3: Boot Lid
Scratched
Over 25mm Not Thru Paint


4: Qtr Panel osr
Chipped
1 To 5



5: Door osr
Dented
Over 2 UpTo 10mm

6: Door osf
Chipped
1 To 5

No Image



7: Wing osf
Scratched
Over 25mm Not Thru Paint


8: Screen Front
Chipped
UpTo 10mm



9: Bonnet
Chipped
1 To 5



10: Bumper Front
Cracked
UpTo 25mm




11: Wing nsf
Scratched
Over 25mm Not Thru Paint



12: Door nsf
Poor Previous Repair
Poor Paint



13: Door nsr
Scratched
Over 25mm Not Thru Paint



14: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK