



VEHICLE INSPECTION REPORT

DY13GKA

Vauxhall Antara 2.2 CDTi SE Nav 5dr [Start Stop]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	18/04/2013	Keys	2	CAP Clean	£1,475.00
Year	2013	Service history	Yes	CAP Average	£1,075.00
Mileage	72,254 Miles Warranted	Service documents	Service Book	CAP Below	£675.00
Fuel Type	Diesel	Number of stamps	8	Gearbox	MANUAL
Colour	GREY	Last service date	23/01/2025	Gears	6
VIN	WOLLJ6EH8CB114668	Last service miles	70,158	Doors	5
Body Style	Hatchback	MOT Due	06/02/2026		

£100 ADDITIONAL FEE LAST SERVICE 23/1/25 @ 70158 MILES (8 SERVICE) BOOK

Tyres

NSF	LANVIGATOR	5.0mm
NSR	BUDGET	6.0mm
OSF	LANVIGATOR	5.0mm
OSR	BUDGET	6.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- PAS
- Radio/CD
- Towbar
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



5: Door nsf
Dented
Between 10mm + 30mm



6: Wheel nsr
Scratched
Over 50mm



7: Door nsr
Dented
Between 10mm + 30mm




8: Qtr Panel nsr
Cracked
Replace



9: Bumper Rear
Insecure
Action Required



10: Bumper Rear Moulding
Scratched (Painted)
Over 25mm Thru Paint



11: Roof
Dented
Between 10mm + 30mm



12: Wheel osr
Scratched
Over 50mm



13: Door osr
Dented
Between 10mm + 30mm



14: Door osf
Dented
Over 30mm



15: Wheel osf
Scratched
Over 50mm



16: Wing osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK