



VEHICLE INSPECTION REPORT

HN12XGZ

Nissan Micra 1.2 Kuro 5dr

| Inspection | | Vehicle | |
|-----------------|----|---------|---------|
| Serious Damage? | No | VAT | Margin |
| | | V5 | Present |



Details

| | | | | | |
|------------|------------------------|--------------------|--------------|-------------|-----------|
| Reg. date | 18/06/2012 | Keys | 2 | CAP Clean | £2,375.00 |
| Year | 2012 | Service history | Yes | CAP Average | £1,900.00 |
| Mileage | 56,376 Miles Warranted | Service documents | Service Book | CAP Below | £1,425.00 |
| Fuel Type | Petrol | Number of stamps | 7 | Gearbox | MANUAL |
| Colour | BLACK | Last service date | 01/05/2021 | Gears | 5 |
| VIN | MDHFBUK13U0100359 | Last service miles | 36,944 | Doors | 5 |
| Body Style | Hatchback | MOT Due | 11/05/2026 | | |

£100 ADDITIONAL FEE LAST SERVICE 1/5/21 @ 36944 MILES (7 SERVICE 4 MAIN DEALER) BOOK

Tyres


| | | |
|-------|-----------|-------|
| NSF | BUDGET | 4.0mm |
| NSR | TRIANGLE | 6.0mm |
| OSF | ROADSTONE | 4.0mm |
| OSR | TRIANGLE | 6.0mm |
| Spare | | |

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front armrest
- Solid Paint
- Isofix child seat anchor points
- Central locking
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- ABS
- Side airbags
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Dented
With Paint Damage



5: Door nsf
Dented
With Paint Damage



6: Door nsr
Dented
With Paint Damage



7: Qtr Panel nsr
Dented
With Paint Damage



8: Wheel nsr
Scratched
Over 50mm



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: Door osr
Dented
With Paint Damage



12: Door osf
Dented
Over 30mm



13: Wheel osf
Scratched
Over 50mm



14: Wing osf
Scratched
Over 25mm Thru Paint



15: Roof
 Scratched
 Over 25mm Thru Paint

Interior

Carpet Condition -
 Seat Condition -

Upholstery Condition -
 Odour -

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| | | | |
|--------------------------|----|--|----|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Windows | OK | Radio | OK |
| Sat nav | OK | Steering | OK |