



VEHICLE INSPECTION REPORT

LG13SDO

Nissan Note 1.4 N-Tec+ 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	28/03/2013	Keys	2	CAP Clean	£1,575.00
Year	2013	Service history	Yes	CAP Average	£1,175.00
Mileage	86,737 Miles Warranted	Service documents	Service Book	CAP Below	£775.00
Fuel Type	Petrol	Number of stamps	10	Gearbox	MANUAL
Colour	BLUE	Last service date	02/07/2024	Gears	5
VIN	SJNFAAE11U2203034	Last service miles	80,754		
Body Style	MPV	MOT Due	Expired		

£100 ADDITIONAL FEE.

Last Service - 02.07.2024 at 80754 miles (10 services)

Tyres

NSF	BUDGET	1.0mm
NSR	LAUFENN	5.0mm
OSF	FALKEN	3.0mm
OSR	LAUFENN	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Metallic Paint
- ESP
- Remote central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Alloy wheels
- PAS
- Radio/CD
- Space saver spare wheel
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Aperture Seal of
Broken
Replace



2: Wheel nsf
Scratched
Over 50mm



3: Wing nsf
Scratched
UpTo 25mm Thru Paint



4: Door Mirror Assy nsf
Broken
Replace



5: Door nsf
Dented
With Paint Damage



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Wheel nsr
Scratched
Over 50mm



8: Qtr Panel nsr
Dented
Over 30mm



9: Bumper Rear
Dented
With Paint Damage



10: Tailgate
Scratched
Over 25mm Thru Paint



11: Qtr Panel osr
Dented
With Paint Damage



12: Wheel osr
Scratched
Over 50mm



13: Door nsr
Scratched
Over 25mm Thru Paint



14: Door osf
Scratched
Over 25mm Thru Paint




15: Wing osf
Scratched
UpTo 25mm Thru Paint



16: Wheel osf
Scratched
Over 50mm



17: Seat Base Cover osf
Scuffed
Over 25mm



18: Tyre nsf
Less Than 1.6mm
Illegal

Interior

Carpet Condition Average
Seat Condition Poor

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK