



VEHICLE INSPECTION REPORT

YG15UBO

Mazda 3 2.2d Sport Nav 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	06/03/2015	Keys	2	CAP Clean	£1,825.00
Year	2015	Service history	Yes	CAP Average	£1,450.00
Mileage	116,505 Miles Warranted	Service documents	Electronic / Online	CAP Below	£1,025.00
Fuel Type	Diesel	Number of stamps	1	Gearbox	MANUAL
Colour	RED	Last service date	25/07/2024	Gears	6
VIN	JMZBM642611185423	Last service miles	113,988	Doors	5
Body Style	Hatchback	MOT Due	04/04/2026		

LAST SERVICE 25/7/24 @ 113,988 MILES (1 SERVICE) ELECTRONIC
SERVICE CONFIRMED BY MARTYN KEMP MOTORS Heavy smoking

Tyres



NSF	BUDGET	5.0mm
NSR	MAXXIS	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Heated front seat
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Bumper Front
Poor Previous Repair
Poor Paint




3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5




5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsr
Chipped
1 To 5



8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Wheel nsr
Scratched
Over 50mm




10: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



11: Bumper Rear
Scratched
Over 100mm Thru Paint



12: Boot Lid
Scratched
Over 25mm Not Thru Paint



13: Qtr Panel osr
Dented
2 Or Less UpTo 10mm




14: Wheel osr
Scratched
Over 50mm



15: Door osr
Dented
Between 10mm + 30mm



16: Door osf
Dented
2 Or Less UpTo 10mm



17: Door osf
Scratched
Over 25mm Not Thru Paint



18: Wing osf
Chipped
1 To 5



19: Wheel osf
Scratched
Over 50mm



20: Bonnet
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	Fault
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK