



46 Brampton Road  
Eastbourne  
BN22 9BN

01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT

**RF07BCE**

## Toyota Prius 1.5 VVTi T Spirit Hybrid 5dr CVT Auto

### Inspection

Serious Damage? No

### Vehicle

VAT Margin

V5 Photocopy

nama  
GRADE  
4

### Details

Reg. date 25/04/2007

Year 2007

Mileage 45,600 Miles  
Warranted

Fuel Type Hybrid Electric

Colour BLUE

VIN JTDKB20U807631135

Body Style Hatchback

Keys 2

Service history Yes

Service documents Printout

Number of stamps 12

Last service date 10/07/2024

Last service miles 44,015

MOT Due 07/10/2025

CAP Clean £3,325.00

CAP Average £2,850.00

CAP Below £2,350.00

Gearbox CVT

Gears 4

Doors 5

£65 ADDITIONAL FEE.

Last service 10/07/2024 at 44,015 miles- 12 services ( 1 main dealer)

Mileage of service on 19/6/14 not recorded  
photocopy of V5

### Tyres

NSF GOODYEAR Worn

NSR GT RADIAL 5.0mm

OSF RAPID 2.0mm

OSR GT RADIAL 5.0mm

Spare

## Features


- Cruise control
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Cloth seat trim
- PAS
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Central locking
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5




2: Bumper Front  
Poor Previous Repair  
Poor Paint



3: Wing nsf  
Chipped  
1 To 5



4: Door nsf  
Dented  
Over 2 UpTo 10mm



5: Door nsf  
Scratched  
Over 25mm Not Thru Paint



6: Door nsr  
Poor Previous Repair  
Poor Paint



7: Qtr Panel nsr  
Poor Previous Repair  
Poor Paint



8: Bumper Rear  
Poor Previous Repair  
Poor Paint



9: Boot Lid  
Poor Previous Repair  
Poor Paint



10: Qtr Panel osr  
Dented  
With Paint Damage




11: Door osr  
Poor Previous Repair  
Poor Paint



12: Door osf  
Poor Previous Repair  
Poor Paint



13: Wing osf  
Chipped  
1 To 5



14: Tyre nsf  
Worn  
Replace

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Clutch Slip Test from Static	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK