



VEHICLE INSPECTION REPORT

LGZ9129

Volkswagen Touran 1.6 TDI 115 SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	24/11/2018	Keys	2	CAP Clean	£9,350.00
Year	2018	Service history	Yes	CAP Average	£8,325.00
Mileage	85,289 Miles Warranted	Service documents	Printout	CAP Below	£7,325.00
Fuel Type	Diesel	Number of stamps	3	Gearbox	MANUAL
Colour	GREY	Last service date	14/10/2021	Gears	6
VIN	WVGZZZ1TZKW010457	Last service miles	45,771		
Body Style	MPV	MOT Due	12/12/2025		

£65 ADDITIONAL FEE. Last service 14/10/2021 at 45,771 miles, 3 MAIN DEALER SERVICES Front parking sensors faulty
Slight rattle while revving

Tyres


NSF	LAUFENN	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	LAUFENN	5.0mm
OSR	LAUFENN	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Drivers airbag
- Traction control
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Metallic Paint
- Passenger airbag
- Cloth seat trim
- PAS
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint

No Image



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



7: Door nsf
Dented
Between 10mm + 30mm



8: Door nsr
Scratched
UpTo 25mm Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Qtr Panel osr
Dented
With Paint Damage



12: Door osr
Dented
Between 10mm + 30mm



13: Door osf
Dented
Between 10mm + 30mm



14: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK