



VEHICLE INSPECTION REPORT

LP08OML

Mercedes-Benz A-Class A150 CLASSIC SE

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

nama
GRADE
3

Details

Reg. date	24/07/2008	Keys	2	CAP Clean	£560.00
Year	2008	Service history	Yes	CAP Average	£220.00
Mileage	146,700 Miles Warranted	Service documents	Service Book	CAP Below	£200.00
Fuel Type	Petrol	Number of stamps	9	Gearbox	MANUAL
Colour	GREY	Last service date	15/05/2024	Gears	5
VIN	WDD1690312J626871	Last service miles	139,026	Doors	5
Body Style	Hatchback	MOT Due	Expired		

£65 ADDITIONAL FEE. EXPIRED MOT.

Last service 15/05/2024 at 139,026 miles, 9 services (6 main dealer services) Only 1 key works

Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- PAS
- Radio/CD
- Climate control
- Rear headrests
- Drivers airbag
- Cloth seat trim
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- Passenger airbag
- Steel wheels
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Central locking
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- ABS
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Chipped
1 To 5



4: Door Mirror Assy nsf
Broken
Replace



5: Door nsf
Chipped
1 To 5



6: Door nsf
Scratched
Over 25mm Not Thru Paint




7: Door nsr
Chipped
1 To 5




8: Qtr Panel nsr
Dented
Between 10mm + 30mm



9: Bumper Rear
 Scratched
 Over 100mm Thru Paint



10: Boot Lid
 Scratched
 Over 25mm Not Thru Paint



11: Qtr Panel osr
 Scratched
 Over 25mm Not Thru Paint



12: Door osr
 Dented
 Over 2 UpTo 10mm



13: Door osr
 Scratched
 UpTo 25mm Thru Paint




14: Door osf
 Chipped
 1 To 5

No Image



15: Door osf
Scratched
Over 25mm Not Thru Paint


16: Wing osf
Chipped
1 To 5



17: Screen Front
Chipped
UpTo 10mm



18: Seat Base Cover osf
Torn
Over 3mm



19: Other
N/A
N/A

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
Airbag light illuminated	Fault	Oil warning light illuminated	OK
ABS light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK