



# VEHICLE INSPECTION REPORT

**CP14OSZ**

## Peugeot 2008 1.6 VTi Allure 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	31/07/2014	Body Style	Hatchback	CAP Below	£1,275.00
Year	2014	Keys	1	Gearbox	MANUAL
Mileage	65,936 Miles Warranted	Service history	None	Gears	5
Fuel Type	Petrol	MOT Due	Expired	Doors	5
Colour	WHITE	CAP Clean	£2,200.00		
VIN	VF3CU5FS0EY081927	CAP Average	£1,750.00		

£100 ADDITIONAL FEE. EXPIRED MOT.

No service history Engine misfire,  
Rough idle

### Tyres

NSF	COMFORSER	5.0mm
NSR	COMFORSER	5.0mm
OSF	COMFORSER	5.0mm
OSR	COMFORSER	5.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Metallic Paint
- ESP
- Central locking
- PAS
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- ABS
- Passenger airbag
- Partial leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Dented  
Between 10mm + 30mm



2: Bumper Front  
Scratched  
Over 100mm Thru Paint





3: Wing nsf  
Dented  
Over 30mm



4: Wheel nsf  
Scratched  
Over 50mm



5: Door nsf  
Scratched  
UpTo 25mm Thru Paint



6: Door nsr  
Dented  
Between 10mm + 30mm



7: Wheel nsr  
Scratched  
Over 50mm



8: Qtr Panel nsr  
Dented  
Between 10mm + 30mm



9: Tailgate  
Dented  
Over 30mm



10: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



11: Wheel osr  
Scratched  
Up To 50mm



12: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



13: Door osr  
Dented  
Between 10mm + 30mm



14: Door osf  
Chipped  
Edge Chip



15: Wheel of  
Scratched  
Over 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK