



VEHICLE INSPECTION REPORT

WV14VCX

Citroen C5 2.2 HDI 16V Exclusive [200] 4dr Auto

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
4

Details

Reg. date 18/03/2014

Year 2014

Mileage 109,710 Miles
Warranted

Fuel Type Diesel

Colour GREY

VIN VF7RD4HLADL517820

Body Style Saloon

Keys 2

Service history Yes

Service documents Service Book

Number of stamps 7

Last service date 10/06/2024

Last service miles 101,444

MOT Due 16/07/2026

CAP Clean £1,825.00

CAP Average £1,425.00

CAP Below £1,000.00

Gearbox AUTOMATIC

Gears 6

Doors 4

£100 ADDITIONAL FEE. LAST SERVICE 10/6/24 @ 101444 MILES (7 SERVICES 6 MAIN DEALER) BOOK
Vibration at idle

Tyres

NSF BUDGET 2.0mm

NSR NEXEN 2.0mm

OSF BUDGET 2.0mm

OSR NEXEN 2.0mm


Spare

Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Electrically adjustable passenger seat
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Audio remote control
- Air conditioning
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Digital radio
- Climate control
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Partial leather seat trim
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front head restraints
- Rear headrests
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Poor Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Over 50mm

No Image



5: Wing nsf
Scratched
Over 25mm Not Thru Paint

6: Door nsf
Chipped
1 To 5

No Image



7: Door nsf
Scratched
Over 25mm Not Thru Paint

8: Door nsr
Chipped
1 To 5

No Image



9: Door nsr
Scratched
Over 25mm Not Thru Paint

10: Door Moulding nsr
Broken
Replace



11: Wheel nsr
Scratched
Over 50mm



12: Qtr Panel nsr
Dented
With Paint Damage



13: Bumper Rear
Scratched
Over 100mm Thru Paint

No Image

14: Boot Lid
Scratched
Over 25mm Not Thru Paint



15: Qtr Panel osr
Dented
Over 30mm



16: Wheel osr
Scratched
Over 50mm



17: Door osr
Dented
With Paint Damage



18: Door osf
Dented
With Paint Damage



19: Wing osf
Poor Previous Repair
Poor Paint



20: Wheel osf
Scratched
Over 50mm



21: Boot Lid
Dented
Between 10mm + 30mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
		Steering	OK