



VEHICLE INSPECTION REPORT

GJ68LNP

Skoda Karoq 1.0 TSI SE Nav Plus 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	27/09/2018	Keys	2	CAP Clean	£9,200.00
Year	2018	Service history	Yes	CAP Average	£8,100.00
Mileage	70,232 Miles Warranted	Service documents	Printout	CAP Below	£7,000.00
Fuel Type	Petrol	Number of stamps	8	Gearbox	MANUAL
Colour	GREEN	Last service date	10/07/2025	Gears	6
VIN	TMBKP7NU7K5010507	Last service miles	69,743		
Body Style	Estate	MOT Due	26/09/2025		

£65 ADDITIONAL FEE. Last service 10/07/2025 at 69743 miles (8 main dealer services).

Tyres

NSF	ROYALBLACK	5.0mm
NSR	BRIDGESTONE	5.0mm
OSF	LAUFENN	4.0mm
OSR	LAUFENN	6.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels
- Cruise control
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Metallic Paint
- ESP
- Central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
UpTo 25mm Thru Paint



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Dented
With Paint Damage



4: Wheel nsf
Scratched
Up To 50mm



5: Door nsf
Scratched
Up To 25mm Thru Paint



6: Door nsr
Dented
With Paint Damage



7: Wheel nsr
Scratched
Over 50mm



8: Qtr Panel nsr
Dented
Over 30mm



9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Tailgate
Scratched
UpTo 25mm Thru Paint



11: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



12: Door osr
Dented
With Paint Damage



13: Door osf
Chipped
Edge Chip



14: Wing osf
Dented
With Paint Damage



15: Wheel osf
Scratched
Up To 50mm



16: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



17: Door Pad osf
Scuffed
UpTo 25mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK