



46 Brampton Road  
Eastbourne  
BN22 9BN

01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT

**DG57SWU**

## Ford C-Max 1.8 Titanium 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	22/11/2007	Keys	2	CAP Clean	£630.00
Year	2007	Service history	Yes	CAP Average	£280.00
Mileage	99,463 Miles Warranted	Service documents	Service Book	CAP Below	£200.00
Fuel Type	Petrol	Number of stamps	14	Gearbox	MANUAL
Colour	GREY	Last service date	04/04/2025	Gears	5
VIN	WF0EXXGCDE7S04631	Last service miles	97,780		
Body Style	MPV	MOT Due	18/04/2026		

Last Service -04.04.2025 at 97780 miles (14 services) High clutch

### Tyres

NSF	BARUM	5.0mm
NSR	BARUM	5.0mm
OSF	TOYO	4.0mm
OSR	BARUM	5.0mm
Spare		

## Features


- PAS
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Rear wiper
- Fixed panoramic glass roof
- Front armrest
- Rear electric windows
- ABS
- Central locking
- Radio/CD
- Front fog lights
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Solid Paint
- Passenger airbag
- Partial leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Scratched  
Over 25mm Thru Paint



2: Carpets Front  
Scuffed  
Over 25mm



3: Switches And Controls  
Broken  
Replace




4: Fascia Trim  
Damaged  
Replace



5: Bumper Front  
Scratched  
Over 100mm Thru Paint



6: Wheel nsf  
Scratched  
Over 50mm



7: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



8: Door Mirror Assy nsf  
Broken  
Replace



9: Door nsf  
Dented  
Over 30mm



10: Door nsr  
Dented  
With Paint Damage



11: Wheel nsr  
Scratched  
Over 50mm



12: Qtr Panel nsr  
Dented  
With Paint Damage



13: Bumper Rear  
Scratched  
Over 100mm Thru Paint




14: Wheel osr  
Scratched  
Over 50mm



15: Qtr Panel osr  
Scratched  
UpTo 25mm Thru Paint



16: Door osr  
Scratched  
Over 25mm Thru Paint



17: Door osf  
Scratched  
Over 25mm Thru Paint



18: Wheel osf  
Scratched  
Over 50mm



19: Wing osf  
Scratched  
UpTo 25mm Thru Paint

## Interior

**Carpet Condition**  
**Seat Condition**

Poor  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	Fault
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK