



VEHICLE INSPECTION REPORT

WO21JWA

DS Ds 3 1.2 PureTech 130 Elegance 5dr EAT8

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	23/07/2021	Keys	2	CAP Clean	£9,725.00
Year	2021	Service history	Yes	CAP Average	£8,625.00
Mileage	33,522 Miles Warranted	Service documents	Printout	CAP Below	£7,525.00
Fuel Type	Petrol	Number of stamps	2	Gearbox	AUTOMATIC
Colour	BLACK	Last service date	17/10/2023	Gears	8
VIN	VR1URHNSSLW019234	Last service miles	17,835	Doors	5
Body Style	Hatchback	MOT Due	30/07/2026		

£100 ADDITIONAL FEE.

Last service 17/10/2023 at 17,835 miles- 2 main dealer services

Tyres


NSF	RAPID	6.0mm
NSR	MICHELIN	5.0mm
OSF	MICHELIN	5.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Cloth seat trim
- Front parking sensor
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Metallic Paint
- ESP
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint




2: Bumper Front
Scratched
Over 100mm Thru Paint

No Image



3: Wing nsf
Scratched
Over 25mm Not Thru Paint

4: Door nsf
Scratched
Over 25mm Thru Paint



5: Door nsr
Scratched
Over 25mm Thru Paint



6: Bumper Rear
Scratched
Over 100mm Thru Paint



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint



8: Door osr
Scratched
Over 25mm Thru Paint



9: Door osf
Chipped
Edge Chip



10: Door osf
Cracked
Replace



11: Roof
Scratched
Over 25mm Thru Paint



12: Wing osf
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK