



# VEHICLE INSPECTION REPORT

**GY65ULF**

## Peugeot 208 1.2 PureTech 82 Active 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	30/11/2015	Keys	2	CAP Clean	£1,900.00
Year	2015	Service history	Yes	CAP Average	£1,475.00
Mileage	62,183 Miles Warranted	Service documents	Service Book	CAP Below	£1,050.00
Fuel Type	Petrol	Number of stamps	8	Gearbox	MANUAL
Colour	GREY	Last service date	20/12/2024	Gears	5
VIN	VF3CAHMZ6FT167152	Last service miles	52,195	Doors	3
Body Style	Hatchback	MOT Due	29/11/2025		

£65 ADDITIONAL FEE. Last service 20/12/2024 at 52,195 miles, 8 services (5 MAIN DEALER)  
Engine very noisy

### Tyres


NSF	SUNNY	3.0mm
NSR	BUDGET	3.0mm
OSF	SUNNY	3.0mm
OSR	BUDGET	4.0mm
Spare		

## Features


- Bluetooth connection
- Rear parking sensor
- Digital radio
- Climate control
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- ABS
- Side airbags
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



No Image



3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint

4: Wheel nsf  
Scratched  
Over 50mm



5: Wing nsf  
Chipped  
1 To 5



6: Door nsf  
Dented  
Over 30mm



7: Qtr Panel nsr  
Dented  
Over 2 UpTo 10mm

No Image

8: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



9: Wheel nsr  
Scratched  
Up To 50mm



10: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



11: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



12: Boot Lid  
Scratched  
Over 25mm Not Thru Paint



13: Boot Lid  
Chipped  
1 To 5



14: Wheel osr  
Scratched  
Up To 50mm




15: Qtr Panel osf  
Dented  
With Paint Damage



16: Door osf  
Chipped  
Multiple Chips



17: Wing osf  
Chipped  
1 To 5



18: Wing osf  
Scratched  
Over 25mm Not Thru Paint



19: Wheel osf  
Scratched  
Up To 50mm



20: Other  
N/A  
N/A



No Image



21: Roof  
Scratched  
Over 25mm Not Thru Paint

22: Screen Front  
Chipped  
UpTo 10mm

### Interior

**Carpet Condition**      Average  
**Seat Condition**      Average

**Upholstery Condition**      Average  
**Odour**      No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK