



VEHICLE INSPECTION REPORT

GL63NZY

Fiat 500 1.2 Lounge 3dr [Start Stop]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/01/2014	Keys	2	CAP Clean	£1,300.00
Year	2014	Service history	Yes	CAP Average	£890.00
Mileage	114,712 Miles Warranted	Service documents	Service Book	CAP Below	£500.00
Fuel Type	Petrol	Number of stamps	4	Gearbox	MANUAL
Colour	WHITE	Last service date	19/12/2020	Gears	5
VIN	ZFA312000J104398	Last service miles	75,266	Doors	3
Body Style	Hatchback	MOT Due	23/10/2025		

LAST SERVICE 19/12/20 @ 75266 MILES (4 SERVICES) BOOK Boot lid faulty

Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- PAS
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Drivers airbag
- Cloth seat trim
- Rear wiper
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Alloy wheels
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Solid Paint
- Central locking
- Audio remote control
- Fixed panoramic glass roof
- Front head restraints
- ABS
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Fogdriving Lamp nsf
Broken
Replace



4: Wing osf
Dented
With Paint Damage




5: Wheel osf
Scratched
Over 50mm



6: Screen Front
Chipped
UpTo 10mm



7: Door osf
Chipped
1 To 5



8: Door osf
Scratched
Over 25mm Not Thru Paint



9: Qtr Panel osr
Dented
Between 10mm + 30mm




10: Wheel osr
Scratched
Over 50mm



11: Other
N/A
N/A



12: Boot Lid
Scratched
Over 25mm Not Thru Paint



13: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



14: Wheel nsr
Scratched
Over 50mm

No Image

No Image

15: Door nsf
Scratched
Over 25mm Not Thru Paint

16: Wing nsf
Scratched
Over 25mm Not Thru Paint



17: Wheel nsf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK