



VEHICLE INSPECTION REPORT

SW59GWP

Citroen C4 1.6HDi 16V VTR Plus [110] 5dr EGS

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	09/02/2010	Keys	2	CAP Clean	£1,025.00
Year	2010	Service history	Yes	CAP Average	£630.00
Mileage	116,596 Miles Warranted	Service documents	Service Book	CAP Below	£275.00
Fuel Type	Diesel	Number of stamps	6	Gearbox	SEMI AUTO
Colour	GREY	Last service date	06/11/2023	Gears	6
VIN	VF7LC9HZHAY503583	Last service miles	110,388	Doors	5
Body Style	Hatchback	MOT Due	25/04/2026		

£100 ADDITIONAL FEE. Last service 06/11/2023 at 110,388 miles, 6 services (2 main dealer) service history is printout and book

Tyres

NSF	BUDGET	5.0mm
NSR	NEXEN	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Cloth seat trim
- PAS
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Central locking
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Sill ns
Rusted
Over 5mm



8: Door nsr
Scratched
UpTo 25mm Thru Paint



9: Qtr Panel nsr
Poor Previous Repair
Rippled UpTo 30%



10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Tailgate
Poor Previous Repair
Rippled UpTo 30%



12: Qtr Panel osr
Rusted
Over 5mm



13: Door osr
Chipped
Edge Chip



14: Door osf
Dented
Over 30mm



15: Wheel osf
Scratched
Over 50mm



16: Wing osf
Chipped
Multiple Chips

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK