



VEHICLE INSPECTION REPORT

GX21KVU

Mazda CX-30 2.0 e-Skyactiv G MHEV SE-L 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	12/08/2021	Keys	2	CAP Clean	£11,100.00
Year	2021	Service history	Yes	CAP Average	£9,950.00
Mileage	38,094 Miles Warranted	Service documents	Printout	CAP Below	£8,750.00
Fuel Type	Petrol	Number of stamps	2	Gearbox	MANUAL
Colour	GREY	Last service date	30/01/2024	Gears	6
VIN	JMZDM6WE600218800	Last service miles	23,142	Doors	5
Body Style	Hatchback	MOT Due	Expired		

£65 ADDITIONAL FEE. EXPIRED MOT

Last service 30/01/2024 at 23,142miles, 2 services (0 main dealer services) Eml and service ligh is on

Tyres

NSF	TRIANGLE	4.0mm
NSR	BUDGET	Damaged
OSF	BRIDGESTONE	Worn
OSR	BRIDGESTONE	2.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Drivers airbag
- Side airbags
- Alloy wheels
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- Metallic Paint
- ESP
- Central locking
- Navigation system
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- PAS
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- ABS
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Scratched
UpTo 25mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



6: Door nsf
Chipped
Edge Chip




7: Door nsr
Scratched
UpTo 25mm Thru Paint



8: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



9: Door osr
Scratched
UpTo 25mm Thru Paint




10: Door osf
Chipped
Edge Chip



11: Wheel osf
Scratched
Over 50mm



12: Tyre nsr
Damaged
Replace



13: Tyre osf
Worn
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	Fault
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK