



VEHICLE INSPECTION REPORT

BX17DNJ

BMW 2 Series 218i SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Buyer To Apply



Details

Reg. date	01/04/2017	Keys	1	CAP Clean	£4,475.00
Year	2017	Service history	Yes	CAP Average	£3,850.00
Mileage	120,829 Miles Warranted	Service documents	Electronic & Paper	CAP Below	£3,225.00
Fuel Type	Petrol	Number of stamps	8	Gearbox	MANUAL
Colour	SILVER	Last service date	09/12/2024	Gears	6
VIN	WBA2D320105H47234	Last service miles	115,652		
Body Style	Estate	MOT Due	19/06/2026		

Last service 09/12/2024 at 115,652 miles, 8 MAIN DEALER SERVICES, part V5 no green slip Exhaust blowing
Drivetrain fault
EML light on
Seat bolt missing from passenger seat
Wrong boot carpet fitted

Tyres		
NSF	CONTINENTAL	5.0mm
NSR	GOODYEAR	3.0mm
OSF	CONTINENTAL	5.0mm
OSR	GOODYEAR	6.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Body coloured bumpers
- Rear electric windows
- Drivers airbag
- Central locking
- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Remote central locking
- Telephone
- Air conditioning
- Metallic Paint
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos




1: Bumper Rear
Poor Previous Repair
Poor Paint



2: Boot Lid
Dented
Over 30mm



3: Roof
Dented
Over 30mm



4: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



5: B Post os
Dented
Over 30mm



6: Door osr
Dented
Over 30mm



7: Wheel osr
Scratched
Over 50mm



8: Door osf
Dented
Over 30mm

No Image



9: Wing osf
Scratched
Over 25mm Not Thru Paint

10: Wheel osf
Scratched
Over 50mm



11: Screen Front
Chipped
UpTo 10mm



12: Bonnet
Dented
With Paint Damage



13: Bumper Front
Poor Previous Repair
Poor Paint



14: Wheel nsf
Scratched
Over 50mm



15: Wing nsf
Dented
With Paint Damage



16: Door nsf
Dented
Over 2 UpTo 10mm



17: Door nsr
Dented
Over 30mm



18: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



19: Wheel nsr
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK