



VEHICLE INSPECTION REPORT

DA62UDG

Skoda Octavia 1.6 TDI CR SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	26/11/2012	Keys	2	CAP Clean	£1,125.00
Year	2012	Service history	Yes	CAP Average	£750.00
Mileage	125,343 Miles Warranted	Service documents	Service Book	CAP Below	£350.00
Fuel Type	Diesel	Number of stamps	7	Gearbox	MANUAL
Colour	GREEN	Last service date	21/06/2022	Gears	5
VIN	TMBCT21Z9D2039032	Last service miles	65,345	Doors	5
Body Style	Hatchback	MOT Due	20/06/2026		

Last service 21/06/2022 at 65,345 miles, 7 services (1 main dealer service) Passenger window faulty

Tyres

NSF	GOODYEAR	5.0mm
NSR	RAPID	5.0mm
OSF	GOODYEAR	5.0mm
OSR	GOODYEAR	6.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Steering wheel mounted controls
- Air conditioning
- Rear electric windows
- ABS
- Passenger airbag
- Cloth seat trim
- PAS
- Digital radio
- Folding rear seats
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- ESP
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Dented
With Paint Damage



4: Wheel nsf
Scratched
Over 50mm



5: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



6: Door nsf
Dented
Between 10mm + 30mm



7: Door nsr
Dented
Between 10mm + 30mm



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Dented
With Paint Damage



10: Tailgate
Dented
Over 30mm



11: Bumper Rear
Dented
With Paint Damage



12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Wheel osr
Scratched
Over 50mm



14: Door osr
Scratched
UpTo 25mm Thru Paint



15: Door osf
Chipped
Edge Chip



16: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	Fault	Radio	OK
Sat nav	OK	Steering	OK