



# VEHICLE INSPECTION REPORT

**YC59OKH**

## Mini Convertible 1.6 Cooper 2dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	27/10/2009	Keys	1	CAP Clean	£1,225.00
Year	2009	Service history	Yes	CAP Average	£830.00
Mileage	94,967 Miles Warranted	Service documents	Printout	CAP Below	£400.00
Fuel Type	Petrol	Number of stamps	1	Gearbox	MANUAL
Colour	BLUE	Last service date	13/12/2013	Gears	6
VIN	WMWMR32090TX75558	Last service miles	25,190		
Body Style	Convertible	MOT Due	Expired		

### EXPIRED MOT.

Last service 13/12/2013 at 25,190 miles, 1 main dealer service Brake warning lights is on, bonnet misaligned

### Tyres


NSF	ACHILLES	2.0mm
NSR	BUDGET	5.0mm
OSF	WESTLAKE	2.0mm
OSR	BUDGET	5.0mm
Spare		

## Features


- Bluetooth connection
- Radio/CD
- Air conditioning
- Rear electric windows
- ABS
- Side airbags
- Alloy wheels
- Heated front seat
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- PAS
- Electric door mirrors
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear parking sensor
- Front fog lights
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Scratched  
Over 25mm Thru Paint



2: Bumper Front  
Scratched  
Over 100mm Thru Paint





3: Wheel osf  
Scratched  
Over 50mm



4: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Thru Paint



5: Door nsf  
Poor Previous Repair  
Poor Paint



6: Wheel nsr  
Scratched  
Over 50mm



7: Qtr Panel nsr  
Poor Previous Repair  
Rippled UpTo 30%



8: Boot Lid  
Dented  
Between 10mm + 30mm





9: Bumper Rear  
Scratched  
Up To 25mm Thru Paint



10: Qtr Panel osr  
Poor Previous Repair  
Rippled UpTo 30%



11: Wheel osr  
Scratched  
Over 50mm




12: Door osf  
Poor Previous Repair  
Rippled UpTo 30%



13: Wheel osf  
Scratched  
Over 50mm



14: Other  
N/A  
N/A



15: Roof Soft Top  
Scuffed  
Over 25mm

16: Fascia Panel  
Missing  
Replace

## Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	Fault	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK