



VEHICLE INSPECTION REPORT

WV09MYM

Nissan Note 1.4 Acenta 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	16/03/2009	Keys	1	CAP Clean	£750.00
Year	2009	Service history	Yes	CAP Average	£350.00
Mileage	132,951 Miles Warranted	Service documents	Electronic / Online	CAP Below	£200.00
Fuel Type	Petrol	Number of stamps	1	Gearbox	MANUAL
Colour	SILVER	Last service date	20/09/2017	Gears	5
VIN	SJNFAAE11U2006213	Last service miles	88,227		
Body Style	MPV	MOT Due	21/07/2026		

Last service 20/09/2017 at 88,227 miles
1 service confirmed by Bexhill Motors Radio locked code required

Tyres

NSF	JOYROAD	5.0mm
NSR	BUDGET	3.0mm
OSF	AVON	5.0mm
OSR	ROVELO	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels
- Cruise control
- Radio/CD
- Air conditioning
- Front head restraints
- Metallic Paint
- ESP
- Central locking
- PAS
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Headrest Assy Rear Seat Centr
Missing
Replace



2: Bonnet
Dented
Over 30mm



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Chipped
Multiple Chips



6: Door nsf
Dented
Over 30mm



7: Door nsr
Dented
Over 30mm



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Bumper Rear
Dented
With Paint Damage



11: Tailgate
Dented
Over 30mm



12: Wheel osr
Scratched
Over 50mm



13: Qtr Panel osr
Dented
Between 10mm + 30mm



14: Door osr
Dented
Between 10mm + 30mm



15: Door osf
Dented
Between 10mm + 30mm



16: Door Mirror Assy osf
Missing
Replace



17: Wheel osf
Scratched
Over 50mm



18: Wing osf
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	Fault
		Steering	OK