



# VEHICLE INSPECTION REPORT

**KS11GYT**

## Peugeot 3008 1.6 HDi 112 Exclusive 5dr EGC

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	22/07/2011	Keys	2	CAP Clean	£890.00
Year	2011	Service history	Yes	CAP Average	£490.00
Mileage	118,763 Miles Warranted	Service documents	Service Book	CAP Below	£200.00
Fuel Type	Diesel	Number of stamps	9	Gearbox	SEMI AUTO
Colour	SILVER	Last service date	22/09/2022	Gears	6
VIN	VF30U9HR8BS200386	Last service miles	93,764	Doors	5
Body Style	Hatchback	MOT Due	21/09/2025		

Last service 22/09/2022 at 93,764 miles, 9 services (4 MAIN DEALER SERVICES) Dpf light warning display

### Tyres

NSF	SUNNY	5.0mm
NSR	TRIANGLE	4.0mm
OSF	RAPID	6.0mm
OSR	TRIANGLE	4.0mm
Spare		

## Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Metallic Paint
- Passenger airbag
- Cloth seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Front parking sensor
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Front armrest
- Rear electric windows
- ABS
- Central locking
- PAS
- Radio/CD
- Front fog lights
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking

## Photos






## Condition Check



## Damage Photos




1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
Over 100mm Thru Paint



3: Wheel nsf  
Scratched  
Over 50mm



4: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



5: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Thru Paint



6: Door nsf  
Scratched  
UpTo 25mm Thru Paint



7: Qtr Panel nsr  
Poor Previous Repair  
Rippled UpTo 30%




8: Bumper Rear  
Scratched  
Over 100mm Thru Paint



9: Tailgate  
Dented  
Between 10mm + 30mm



10: Qtr Panel osr  
Dented  
Over 30mm



11: Door osr  
Scratched  
UpTo 25mm Thru Paint



12: Door osf  
Scratched  
Over 25mm Thru Paint



13: Wheel osf  
Scratched  
Over 50mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK