



# VEHICLE INSPECTION REPORT

**GL10GHU**

## Volkswagen Golf 1.6 TDi 105 SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	26/05/2010	Service history	Yes	CAP Average	£1,175.00
Year	2010	Service documents	Service Book	CAP Below	£775.00
Mileage	100,724 Miles Warranted	Number of stamps	6	Gearbox	MANUAL
Fuel Type	Diesel	Last service date	16/04/2021	Gears	5
Colour	BLUE	Last service miles	82,938	Doors	5
VIN	WVWZZZ1KZAP160701	MOT Due	Expired		
Body Style	Hatchback	CAP Clean	£1,575.00		

£65 ADDITIONAL FEE. Last service 16/04/2021 at 82,938 miles, 6 MAIN DEALER SERVICES Eml light is on, engine shake while idle

### Tyres

NSF	MICHELIN	5.0mm
NSR	CONTINENTAL	4.0mm
OSF	MICHELIN	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

## Features


- Cruise control
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Isofix child seat anchor points
- Central locking
- PAS
- Electric door mirrors
- Front electric windows
- Rear headrests
- Curtain airbags
- Passenger airbag
- Remote central locking
- Rear wiper
- Air conditioning
- Front head restraints
- Metallic Paint
- Drivers airbag
- Rear airbags
- Cloth seat trim
- Radio/CD
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- ESP
- Side airbags
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Chipped  
Multiple Chips





3: Wheel nsf  
Scratched  
Over 50mm



4: Wing nsf  
Chipped  
1 To 5



5: Door nsf  
Dented  
Between 10mm + 30mm



6: Sill ns  
Dented  
Over 30mm



7: Door nsr  
Dented  
Over 30mm



8: Wheel nsr  
Scratched  
Over 50mm





9: Qtr Panel nsr  
Dented  
Between 10mm + 30mm



10: Bumper Rear  
Scratched  
Over 100mm Thru Paint



11: Tailgate  
Scratched  
Over 25mm Thru Paint



12: Qtr Panel osr  
Dented  
With Paint Damage



13: Wheel osr  
Scratched  
Over 50mm



14: Door osr  
Dented  
With Paint Damage






15: Door osf  
Dented  
Over 30mm



16: Wheel osf  
Scratched  
Over 50mm



17: Wing osf  
Scratched  
Over 25mm Thru Paint



18: Screen Front  
Chipped  
UpTo 10mm

## Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK