



VEHICLE INSPECTION REPORT

AP68KUS

Honda Civic 1.0 VTEC Turbo 126 Sport Line 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	27/12/2018	Keys	2	CAP Clean	£9,650.00
Year	2018	Service history	Yes	CAP Average	£8,575.00
Mileage	48,098 Miles Warranted	Service documents	Service Book	CAP Below	£7,575.00
Fuel Type	Petrol	Number of stamps	6	Gearbox	MANUAL
Colour	RED	Last service date	12/08/2024	Gears	6
VIN	SHHFK6700JU011129	Last service miles	46,447	Doors	5
Body Style	Hatchback	MOT Due	30/12/2025		

Last service 12/08/2024 at 46447 miles (6 main dealer services)
Timing belt replaced 12/08/2024. Esp warning light on , steering wheel warning lights on , acc warning light on

Tyres

NSF
NSR
OSF
OSR
Spare

Features


- Bluetooth connection
- Park assist camera
- Digital radio
- Air conditioning
- Front head restraints
- Metallic Paint
- Curtain airbags
- Passenger airbag
- Alloy wheels
- Cruise control
- PAS
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Drivers airbag
- Central locking
- Front parking sensor
- Rear parking sensor
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- ESP
- Remote central locking
- Navigation system
- Rear wiper
- Front fog lights
- Front electric windows
- Rear headrests
- Collision avoidance braking
- Isofix child seat anchor points
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
1 To 5



3: Wheel osf
Scratched
Over 50mm



4: Handle Outer nsf
Scratched (Painted)
UpTo 25mm Thru Paint



5: Handle Outer nsr
Scratched (Painted)
UpTo 25mm Thru Paint



6: Wheel osr
Scratched
Over 50mm




7: Bumper Rear
Scratched
25 to 100mm Thru Paint




8: Wheel osr
Scratched
Over 50mm



9: Door osr
Chipped
1 To 5




10: Door osf
Scratched
Over 25mm Not Thru Paint



11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



12: Wheel nsf
Scratched
Over 50mm



13: Wing osf
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	Fault	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK