



# VEHICLE INSPECTION REPORT

**NV58AVN**

## Kia Ceed 1.6 GS 5dr

### Inspection

Serious Damage? No

### Vehicle

VAT Margin

V5 Present

nama  
GRADE  
**5**

### Details

Reg. date 17/02/2009

Year 2009

Mileage 112,704 Miles  
Warranted

Fuel Type Petrol

Colour BLUE

VIN U5YFF24229L145065

Body Style Hatchback

Keys 1

Service history Yes

Service documents Service Book

Number of stamps 6

Last service date 28/11/2015

Last service miles 32,717

MOT Due 15/06/2026

CAP Clean £770.00

CAP Average £370.00

CAP Below £200.00

Gearbox MANUAL

Gears 5

Doors 5

LAST SERVICE 28/11/15 @ 32717 MILES (6 SERVICES 4 MAIN DEALER) BOOK  
INPUT ERROR OF MILEAGE IN 2023 Rear brakes gridding

### Tyres

NSF BUDGET Damaged

NSR SAILUN 5.0mm

OSF NEXEN 5.0mm

OSR BUDGET 5.0mm


Spare

## Features


- PAS
- Body coloured bumpers
- Front armrest
- Rear headrests
- Curtain airbags
- Rear airbags
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- Metallic Paint
- Drivers airbag
- Side airbags
- Alloy wheels
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Radio/CD
- Folding rear seats
- Height adjustable drivers seat
- ABS
- Passenger airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Scratched  
Over 25mm Thru Paint



2: Bumper Front  
Scratched  
Over 100mm Thru Paint





3: Wheel nsf  
Scratched  
Over 50mm



4: Wing nsf  
Chipped  
1 To 5



5: A Post ns  
Scratched  
Over 25mm Thru Paint



6: Roof  
Scratched  
Over 25mm Thru Paint



7: Door nsf  
Dented  
With Paint Damage



8: Door nsr  
Dented  
Over 30mm





9: Wheel nsr  
Scratched  
Over 50mm



10: Qtr Panel nsr  
Dented  
With Paint Damage



11: Bumper Rear  
Poor Previous Repair  
Paint Flake



12: Wheel osr  
Scratched  
Over 50mm



13: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



14: Door osr  
Scratched  
Over 25mm Thru Paint



15: Door osf  
Scratched  
Over 25mm Thru Paint



16: Wheel osf  
Scratched  
Over 50mm



17: Wing osf  
Scratched  
Over 25mm Thru Paint



18: Tyre nsf  
Damaged  
Replace

**Interior**

**Carpet Condition**      Poor  
**Seat Condition**      Average

**Upholstery Condition**      Average  
**Odour**      No

**Vehicle Inspection Report**

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	Fault	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK