



VEHICLE INSPECTION REPORT

GV64LGO

Dacia Sandero Stepway 0.9 TCe Laureate 5dr

nama
GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	16/01/2015	Keys	2	CAP Clean	£2,375.00
Year	2015	Service history	Yes	CAP Average	£1,925.00
Mileage	57,964 Miles Warranted	Service documents	Service Book	CAP Below	£1,500.00
Fuel Type	Petrol	Number of stamps	3	Gearbox	MANUAL
Colour	BLACK	Last service date	20/01/2020	Gears	5
VIN	UU15SDAAC52091712	Last service miles	31,020	Doors	5
Body Style	Hatchback	MOT Due	08/12/2025		

LAST SERVICE 20/1/20 @31020 MILES (3 SERVICES 2 MAIN DEALER) BOOK Front wipers not working, boot will not open

Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	5.0mm
OSF	FIRESTONE	3.0mm
OSR	BUDGET	5.0mm


Spare

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- ABS
- Passenger airbag
- Cloth seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Steel wheels
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Metallic Paint
- ESP
- Central locking
- PAS
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bumper Front
Chipped
Multiple Chips



2: Bonnet
Scratched
Over 25mm Thru Paint



3: Wheel Trim nsf
Missing
Replace



4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Door nsf
Chipped
Edge Chip



6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Door osr
Scratched
Over 25mm Thru Paint



9: Door osf
Chipped
Edge Chip



10: Wing osf
Scratched
Over 25mm Thru Paint



11: Tailgate
Dented
Between 10mm + 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK