



VEHICLE INSPECTION REPORT

GU65WUA

Vauxhall Corsa 1.4 ecoFLEX Energy 3dr [AC]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	23/10/2015	Keys	1	CAP Clean	£3,200.00
Year	2015	Service history	Yes	CAP Average	£2,700.00
Mileage	62,672 Miles Warranted	Service documents	Service Book	CAP Below	£2,225.00
Fuel Type	Petrol	Number of stamps	2	Gearbox	MANUAL
Colour	GREY	Last service date	12/10/2017	Gears	5
VIN	W0L0XEP08G6006629	Last service miles	10,428	Doors	3
Body Style	Hatchback	MOT Due	19/12/2025		

LAST SERVICE 12/10/17 @ 10428 MILES (2 MAIN DEALER) BOOK Car bumps when in reverse
Coolant pipe popped of and thermostat housing snapped

Tyres

NSF	BRIDGESTONE	1.0mm
NSR	BUDGET	5.0mm
OSF	CONTINENTAL	Damaged
OSR	HANKOOK	5.0mm
Spare		

Features


- Bluetooth connection
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Drivers airbag
- Central locking
- Cruise control
- Body coloured bumpers
- Folding rear seats
- Metallic Paint
- ESP
- Remote central locking
- PAS
- Electric door mirrors
- Front electric windows
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Cloth seat trim
- Rear wiper
- Front fog lights
- Front head restraints
- ABS
- Passenger airbag
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Over 30mm



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Dented
Over 2 UpTo 10mm



5: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



6: Door nsf
Dented
Over 30mm



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



8: Bumper Rear
Scratched
Over 100mm Thru Paint



9: Wheel osr
Scratched
Over 50mm



10: Qtr Panel osr
Dented
With Paint Damage




11: Door osf
Scratched
Over 25mm Thru Paint



12: Wing osf
Scratched
UpTo 25mm Thru Paint



13: Wheel osf
Scratched
Over 50mm



14: Tyre nsf
Less Than 1.6mm
Illegal

No Image

No Image

15: Tyre osf
Damaged
Replace

16: Tyre nsf
Less Than 1.6mm
Illegal

No Image

17: Tyre osf
Damaged
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	Fault
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK