



46 Brampton Road  
Eastbourne  
BN22 9BN

01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT

**GF23JGV**

## Volkswagen T-Roc 1.5 TSI Life 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	30/03/2023	Keys	2	CAP Average	£16,550.00
Year	2023	Service history	Yes	CAP Below	£15,200.00
Mileage	25,929 Miles Warranted	Service documents	Printout	Gearbox	MANUAL
Fuel Type	Petrol	Number of stamps	1	Gears	6
Colour	BLACK	Last service date	11/10/2024	Doors	5
VIN	WVGZZZA1ZPV658268	Last service miles	17,460		
Body Style	Hatchback	CAP Clean	£17,900.00		

£65 ADDITIONAL FEE. Last service 11/10/2024 at 17460 miles (1 main dealer service).

### Tyres

NSF	BUDGET	5.0mm
NSR	FALKEN	4.0mm
OSF	BUDGET	5.0mm
OSR	FALKEN	5.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
Multiple Chips



No Image

3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



4: Wheel nsf  
Scratched  
Over 50mm

No Image

5: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



6: Door nsf  
Chipped  
1 To 5

No Image

7: Door nsf  
Scratched  
Over 25mm Not Thru Paint

No Image

8: Door nsr  
Scratched  
Over 25mm Not Thru Paint



9: Wheel nsr  
Scratched  
Up To 50mm

No Image

10: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



11: Bumper Rear  
Chipped  
Multiple Chips

No Image

12: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint

No Image

13: Boot Lid  
Scratched  
Over 25mm Not Thru Paint



14: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



15: Wheel osr  
Scratched  
Over 50mm



16: Door osr  
Scratched  
Over 25mm Thru Paint



17: Door osf  
Scratched  
Over 25mm Thru Paint



18: Wing osf  
Scratched  
Over 25mm Thru Paint



19: Wheel osf  
Scratched  
Up To 50mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK